TEST REPORT

Name of product: Standing mailbox

Client Name: Suzhou Hongmao Import & Export Trade Co.,Ltd

Test sort: Client Test

Report number: SZQLAB-20251738A

Suzhou SZQ Testing Co., Ltd.

Address: Building 1, No.3-2, Dongwu South Road, Wuzhong Economic Development Zone, Suzhou
TEL:0512-68796618 P.C.:215000
Internet:http://www.szqlab.com E-Mail:cs@szqlab.com

Product Name	Standing mailbox	Trademark	/
Model No.	HPB932LB2-SP1-01	Product ID/S.N	/
Client Name	Suzhou Hongmao Import & Export Trade Co.,Ltd	Contact	15988833449
Client Address	Floor 2, Building A, No.1899, Songjia Road , Wuzhong District, Suzhou City		
Manufacturer	Suzhou Hongmao Import & Export Trade Co.,Ltd	Contact	/
Sampling	Sample delivery	Received date	2025.12.25
Sample status	Good	Number of Sample	1pc
Sample No.	20251225008A	Test Date	2025.12.26-2026.02.11
Environmental Conditions	Ambient Temperature：（20-25）℃, Relative Humidity：（50-56）%RH, Atmospheric pressure：（100.8-101.2）kPa		

Test basis:
IEC 60068-2-64:2019《Environmental testing - Part 2-64: Tests - Test Fh: Vibration, broadband random and guidance》
IEC 60529:2013《Degrees of protection provided by enclosures(IP Code)》

Judgment basis:
IEC 60529:2013 《Degrees of protection provided by enclosures(IP Code)》
《Enterprise Technical Specifications》

Test Conclusion：
The sample was tested and the inspected items met the requirements of IEC 60529:2013 and 《Enterprise Technical Specifications》

（Testing company signature）
2026.03.30(Y.M.D)

Suggestions：/

Editor：	Auditor：	Approver：
Tengkai Chu	Shuaihua Li	Linden Cui
2026.03.30	2026.03.30	2026.03.30

Summary of testing items				
No.	Test items		Test basis	Remark
1	Environment	Random Vibration Test	IEC 60068-2-64:2019	—
2		IP	IEC 60529:2013	—

Blank below

Test results				
No.	Testing items	Test basis and requirements	Test Result	Verdict
1	Random Vibration Test	Frequency: 20-100Hz; Accelerated Spectral Density: 1.0（m/s^2）^{2}/Hz; Frequency: 500Hz Accelerated Spectral Density: 0.3（m/s^2）^{2}/Hz; The samples should remain intact after being tested for 20 minutes on each of the X, Y, and Z axes After the test, the packaging should be undamaged.	The packaging is undamaged The sample appears undamaged	Pass
2	IP	The sample battery compartment shall be evaluated shall meet the requirements of IPX4.	The battery compartment of this sample meets IPX4.	Pass

Blank below

Sample Photos



Appearance



IPX4 Test Photo

Sample Photos



After IPX4 test Photo



X-axis random vibration test Photo

Sample Photos



Y-axis random vibration test Photo



Z-axis random vibration test Photo

Main Instrumentation List

No.	Name of Instrumentation	Model	Serial Number	Calibration Due Date	Use(√)
1	Waterproof Test System	IPX1-7	NT-003	2026.07.30	√
2	Electromagnetic Vibration Test System	RI6C-LT1515-HEQ1515	FO-016	2026.03.31	√

Note：The above Instrumentation in verification cycle all normally work。

——THE END——

STATEMENT

1. The report is invalid if it is not stamped with the "Special Seal for Testing" or "Special Seal for Riding Seams".

2. The report is invalid without the signature of the Editor, Auditor, and approver.

3. Invalid report if altered.

4. The testing conclusion of the self sent sample is only valid for the submitted sample, and the testing results are for the purpose of understanding the quality of the sample.

5. The items marked with "*" in the inspection items are subcontracting inspection items, and the items marked with "☆" are not within the scope of CNAS recognition.

6. The report without the qualification certification mark (CMA) is only used for scientific research, teaching, or internal quality control purposes.

7. Partial reproduction of this report is not allowed without the written consent of our laboratory.

8. If you have any objections to the testing report, please submit it to our unit within 15 days from the date of receiving the report. Failure to do so will not be accepted.

9. The tested samples must be collected within three months of receiving the inspection report. If they are not collected after the deadline, the testing unit will handle it on its own.

Suzhou SZQ Testing Co., Ltd.

Address: Building 1,No.3-2,Dongwu South Road,Wuzhong Economic Development Zone, Suzhou

TEL:0512-68796618 P.C.:215000

Internet:http://www.szqlab.com

E-Mail:cs@szqlab.com